

CPYRGHT

Vegas-Area Mishaps

Air Force jet pilots escaped death yesterday in separate accidents to malfunctioning equipment. Robert E. Wilcox, from his F-100 Super after reporting a malfunction. He parachuted into Atomic Energy Commission's rigidly guarded experimental area at Groom Lake, 100 miles north of here and was turned to the base in good condition by helicopter. The other mishap occurred at the Indian Springs Air Force Base, 45 miles north of here when 1st Lt. Donald Murgatroyd was forced into the runway carrier when his landing gear failed to function. He also

Vegas-Area Mishaps

Air Force jet pilots escaped death yesterday in separate accidents to malfunctioning equipment. Robert E. Wilcox, from his F-100 Super after reporting a malfunction. He parachuted into Atomic Energy Commission's rigidly guarded experimental area at Groom Lake, 100 miles north of here and was turned to the base in good condition by helicopter. The other mishap occurred at the Indian Springs Air Force Base, 45 miles north of here when 1st Lt. Donald Murgatroyd was forced into the runway carrier when his landing gear failed to function. He also

Ape Deal Accidents

3 AIR FORCE BASE
rich (UPI)—Two jet pilots narrowly escaped death today in accidents blamed on malfunctioning equipment. Robert E. Wilcox, from his F-100 Super, reporting a malfunction. He parachuted into Atomic Energy Commission's rigidly guarded experimental area at Groom Lake, 100 miles north of Las Vegas, and was returned to the base in good condition by helicopter.

The other mishap occurred at the Indian Springs Air Force Base, 45 miles north of Las Vegas, when 1st Lt. Donald Murgatroyd was forced into the runway carrier when his landing gear failed to function. He also

Injury from Accidental Mishaps

At Nellis Air Force Base this morning in a series of accidents involving F-4 Sabres, one pilot bailed out and the other riding his chute through a crash barrier at Indian Springs Air Force Base. Lieutenant Robert Wilcox ejected from his F-100 after reporting a "malfunction" and landed safely in a field about five miles north of Groom Lake, about 100 miles north of Las Vegas.

Atomic Energy Commission personnel in the area reported they had the pilot and were trying to get him out of the desert to a point where he could be picked up by Nellis rescue personnel.

The second, almost simultaneous accident, 1st Lt. Donald Murgatroyd crashed through the landing barrier at Indian Springs base when